

Oil Field Environmental Incident Summary

Incident: 20140325101619 **Date/Time of Notice:** 03/25/2014 10:16
Responsible Party: ENDURO OPERATING, LLC
Well Operator: ENDURO OPERATING, LLC
Well Name: WINDERL 1R
Field Name: GLENBURN **Well File #:** 10166
Date Incident: 3/14/2014 **Time Incident:** 13:45 **Facility ID Number:**
County: RENVILLE **Twp:** 158 **Rng:** 81 **Sec:** 6 **Qtr:**
Location Description: CTB

Submitted By: Bryan Pease **Received By:**

Contact Person: Bryan Pease
777 MAIN STREET
SUITE 800
FORT WORTH, TX 76102

General Land Use: Well/Facility Site **Affected Medium:** Well/Facility Soil

Distance Nearest Occupied Building: 0.5 Mile

Distance Nearest Water Well:

Type of Incident Tank Leak

Release Contained in Dike Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	5	Barrels	5	Barrels		
Brine	15	Barrels	15	Barrels		

Other

Description of Other Released Contaminant:

Inspected: **Written Report Received:** **Clean Up Concluded:**

Risk Evaluation:

NONE

Areal Extent:

Potential Environmental Impacts:

NONE

Action Taken or Planned:

Sucked up Brine with water truck, Cleaned up oil with skid steer.

Wastes Disposal Location: Brine went to SWD, oil went to Prairie Disposal.

Agencies Involved:

Updates

Date: 3/30/2014

Status: Reviewed; O&G Lead

Staff: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank leak, remained on location within the diking, according to the report. NDIC retains oversight.